



# Release Notes - NRSW 4.6.0.108

---

**Project Name:** NRSW

## Abstract:

This document represents the release note for NetModule Router Software 4.6.0.108. It informs on new functionality, corrections and known issues of this software version of NetModule's router series.

## Keywords:

Netmodule AG, Software Development, NRSW, Release Notes

## Document Control:

<b>Document:</b>	<b>Version</b>	1.0
	<b>File</b>	NRSW-RN-4.6.0.108
	<b>Status</b>	Final
<b>Creation:</b>	<b>Role</b>	<b>Name</b>
	Author	Felix Kopf
	Review	Matthias Fricker
<b>Approval</b>	<b>Role</b>	<b>Name</b>
	Director Product Development	Benjamin Amsler

## 1 Release Information

---

### NetModule Router Software:

Version: **4.6.0.108**  
Date: **Jul 25, 2024**

### Supported Hardware:

NetModule Router	Hardware Version
NB800	V2.0 - V2.2, V3.2 (Rev.B02 - B03)
NG800	V3.0 - V3.2
NB1601	V1.0 - V1.7
NB1800	V2.4 - V2.6
NB1810	V2.4 - V2.6
NB2800	V1.0 - V1.4
NB2810	V1.2
NB3701	V1.0 - V1.10
NB3800	V1.0 - V1.10

### Unsupported Hardware:

- NetModule Router**
- NB1300 Series
  - NB1600 Series
  - NB2200 Series
  - NB2300 Series
  - NB2500 Series
  - NB2600 Series
  - NB2700 Series
  - NB3700 Series
  - NB3711

**NetModule Insights**  
Subscribe to our mailing and get the latest news  
about software releases and much more



## 2 Fixes

---

The following issues and problems have been fixed.

Case-#	Description
<b>413946</b>	<b>Software updates fixes</b> Automatic NRSW updates could not be disabled for some versions. This is fixed.
<b>453829</b>	<b>SDK improvements</b> There has been a memory leak in the SDK modbus implementation which caused problems in long running scripts. This is fixed.
<b>460758</b>	<b>Surveyor improvements</b> Under some circumstances it could be that the watchdog was not triggered by the surveyor within the timeout and therefore the ping mechanism of the surveyor was displayed as dead. This could happen especially while using 4 LTE cards at the same time. This has been fixed.
<b>467124</b>	<b>Web-UI fixes</b> On some configuration pages the progress bar finished before the page was actually ready when applying an configuration change. This is fixed.
<b>475830</b>	<b>SIP fixes</b> The restrictions for incoming SIP calls were too restrictive resulting in rejected invites when called from external SIP phone. This is fixed.
<b>503970</b>	<b>Firewall improvements</b> Existing UDP streams would break on Firewall restart in some cases. This is fixed.

### **3 OSS Notice**

---

See User Manual Chapter OSS.

## 4 Change History

---

Version	Date	Name	Reason
1.0	Jul 25, 2024	Felix Kopf	Final version

### Copyright © 1998 - 2024 Netmodule AG. All rights reserved

The performance features described here are binding only if they have been expressly agreed when the contract was made. This document was produced by Netmodule AG according to the best of the company's knowledge. Netmodule AG reserves the right to change the contents of this document without prior notice. Netmodule AG can give no guarantee in respect of the correctness or accuracy of the information in this document.

Netmodule AG can accept no responsibility for damages, resulting from the use of the network components or the associated operating software. In addition, we refer to the conditions of use specified in the license contract.

Netmodule AG is located at:

Maulbeerstrasse 10  
CH-3011 Bern  
Switzerland  
[info@netmodule.com](mailto:info@netmodule.com)  
Tel +41 31 985 25 10  
Fax +41 31 985 25 11

For more information about Netmodule AG visit the website at [www.netmodule.com](http://www.netmodule.com).