

Release Note NRSW 4.4.0.101

Project Name: NRSW

Abstract:

This document represents the release note for NetModule Router Software 4.4.0.101. It informs on new functionality, corrections and known issues of this software version of NetModule's router series in comparison to release 4.3.0.102.

Keywords:

NetModule, Software Development, NRSW, Release Note

Document Control:

Document:	Version	1.0
	File	NRSW-RN-4.4.0.101
	Status	Valid
Creation:	Role	Name
	Author	Moritz Rosenthal
	Review	Benjamin Amsler
Approval	Role	Name
	Director Product Development	Michael Enz

1 Release Information

NetModule Router Software:

Version: **4.4.0.101**
Date: **October 31, 2019**

Supported Hardware:

NetModule Router	Hardware Version
NB800	V2.0 - V2.2, V3.2 (Rev. B02)
NB1600	V1.0 - V3.3
NB1601	V1.0 - V1.3
NB1800	V2.4 - V2.6
NB1810	V2.4 - V2.6
NB2700	V1.0 - V2.7
NB2710	V1.0 - V2.7
NB2800	V1.0 - V1.4
NB3700	V2.0 - V4.4
NB3701	V1.0 - V1.4
NB3710	V2.0 - V4.3
NB3711	V1.0 - V1.4
NB3720	V2.0 - V4.3
NB3800	V1.0 - V1.4

Unsupported Hardware:

NetModule Router
NB1300 Series
NB2200 Series
NB2300 Series
NB2500 Series
NB2600 Series



NetModule Insights

Subscribe to our mailing and get the latest news about software releases and much more

2 New Features

Case-#	Description
41357	GUI improvements Redundant settings for HTTP, HTTPS and telnet were removed. These services are now managed via Services setup.
45995 51824 57961 59624	SDK improvements BLE scanning and advertising can now be used from SDK scripts. New function <code>usleep()</code> provides sub second sleep intervals. New API function to <code>nb_syslog_p()</code> for logging to different log levels.
55368	GNSS dead-reckoning New configuration options to store and load GNSS DR calibration data to the GNSS module for faster DR learning and better DR data basis.
56066	SNMP service improvements System temperature is now provided on SNMP poll.
57895	Added support for certificate chains for OpenVPN export mode configuration It is possible now to install certificate chains for OpenVPN using the expert mode configuration process.
57900	Support for NB800 Rev. B02 Software support for NB800 Rev. B02 with TOBY-L2xx modem.
58272	WLAN BSS load element The WLAN beacon will show the BSS load element now. The field is helpful for roaming clients to select an AP.
58465	Netflow interface supervision for Ethernet and WWAN interfaces Netflow was introduced for WLAN interfaces and is now available for other device types like Ethernet and WWAN as well.
58969	MQTT Broker A MQTT Broker can now configured on Netmodule Routers providing MQTT service to the network.
59359	Key-parameter support for GRE tunnels GRE tunnels now support the Key-parameter which is used to separate different GRE tunnels between two end-points.

3 Fixes

The following issues and problems have been fixed.

Case-#	Description
56086	Watchdog on failing SDK script did not work A change in the watchdog API was not properly handled by the SDK scripting engine. Resulting in watchdog to fail to restart the System on error. This was fixed.
56374	Problems on switch-over between WAN and WWAN Under rare conditions the switch over between WAN and WWAN did not work as expected.
56972	Ethernet performance Fixed low throughput problem on ethernet ports of NB3701 and NB3711.
57584	Time synchronization required after reboot on NB2700 The system time was not recovered correctly from the internal RTC after soft-reboot, which made an additional time synchronization from an external source (NTP, GNSS) mandatory. This was fixed.
57659	Time synchronization with GNSS could fail On devices equipped with Sierra Wireless MC7455 the time synchronization with GNSS failed. This was fixed in gpsd.
57675 58339 58544 58697 58698 59424	GUI improvements The GUI failed to set some special characters like '&'. If VLAN is configured on bridge devices the bridge interfaces showed up several times in the web GUI. This was fixed. Due to a mistake in the input sanity check it was not possible to change some user options without changing the user's password. This was fixed. For actions which require the actual password which is normally stored only as salted hash, it is still required to provide the password, but this (new) password may be the same as the old one. Due to a failure in string escaping functionality some AT commands failed, which can be issued from the web interface for debug purpose. This was fixed. Fixed typo
57783	IPsec tunnels failed to start Due to timing issues on setups with several IPsec tunnels some of these sometimes failed to start. The start procedure was changed to prevent this failure.
58034	NB2710 failed to start up 2nd WWAN module The 2nd WWAN module on NB2710 would not come up with recent NRSW releases. This was fixed.
58318	Old configuration files failed to apply Some very old configuration files failed to apply with error message 'Unable to create backup'. This was fixed.
58525	Bridge interface lost on software update Software bridge interfaces (like BR1, BR2) might get lost on SW-Update and needed to be reconfigured after the update was finished. This was fixed and the bridge interfaces are preserved on software update.
59020	Storage date of last "Factory Default Config" is not updated on consecutive storage events If the function to store the current configuration as factory default is called several times, the timestamp of the latest store event is not updated. This was fixed.
59053	SDK improvements nb_dio_count failed to remove obsolete data resulting in wrong data. This was fixed.
59054	GNSS data show up delayed We have seen GNSS data to be delayed by some seconds due to a failure in buffer handling. This was fixed.

Case-#	Description
59383	4G-only WWAN connection failed to connect Under certain conditions LTE modules failed to connect if 4G-only was selected even though LTE network was available. That was fixed.
59399	Unstable WWAN connection with LTE-First setting With LTE-First some LTE modules failed to establish connection under poor LTE conditions on software release 4.3.0.102. This was fixed.
59453	Connection tracking for FTP service missing On software releases since 4.3.0.100 the connection tracking for FTP was not configured correctly. This was fixed.
59833	WLAN configuration The WLAN configuration could break on software update to 4.4.0.100 and 4.3.0.103. This has been fixed.

4 ECC conversion

The flash on NB1600, NB2700, NB2710, NB3700, NB3710 and NB3720 provides an automated error correction using ECC. With release 4.1.0.100 we changed the ECC length from 1-bit ECC to 4-bit ECC which provides better error correction. On first boot after the update was performed the data on the flash is automatically converted to use the new ECC setup. While this conversion is performed the LEDs show a running light for about 30 seconds.

If you switch back to an older software release like 4.0.0 the migration is reverted.

We tested updates and down-grades to and from 4.0.0 and 3.8.0. Updates to or from older versions are not supported. If you run an older release or want to downgrade to an older release or a feature release like 3.8.2 you are advised to migrate via 4.0.0 as an intermediate release.

To revert the migration on downgrade the SPL boot loader release 4.1.0 stays in place. It can be downgraded in a second software update process initiated from the target release after the first reboot.

Software updates with recovery images require special attention. You must not use recovery images 4.0.0 and older for systems running 4.1.0 and newer. If you want to use recovery images please contact our support at router@support.netmodule.com.

5 OSS Notice

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)¹, GNU Lesser General Public License (LGPL)² or other open source licenses³.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at router@support.netmodule.com.

¹GPLv2 license is available at <http://www.gnu.org/licenses/gpl-2.0.txt>

²LGPL license is available at <http://www.gnu.org/licenses/lgpl.txt>

³OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at <http://opensource.org/licenses>

6 Change History

Version	Date	Name	Reason
1.0	October 31, 2019	Moritz Rosenthal	Final

Copyright © 1998 - 2019 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG.

All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Maulbeerstrasse 10
 CH-3011 Bern
 Switzerland
info@netmodule.com
 Tel +41 31 985 25 10
 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at www.netmodule.com.