

Meriedweg 11
CH-3172 Niederwangen
Switzerland
info@netmodule.com
http://www.netmodule.com
Tel +41 31 985 25 10
Fax +41 31 985 25 11

Release Note NRSW 3.7.0.104

Project Name: NRSW 3.7

Abstract:

This document represents the release note for NetModule Router Software 3.7.0.104. It informs on new functionality, corrections and known issues of the current software version of NetModule's router series.

Keywords:

NetModule, Software Development, NRSW, Release Note

Document Control:

Document: Version		1.0
	File	NRSW-RN-3.7.0.104
	Status	Valid

Creation:RoleNameAuthorSamuel HessReviewStefan Schlosser

Approval Role Name

Executive VP Products Thomas Siegrist



1 Release Information

NetModule Router Software:

Version: **3.7.0.104**

Date: **January 28, 2015**

Supported Hardware:

NetModule Router Hardware Version

NB1600V1.0 - V3.1NB2700V1.0 - V2.4NB3700V2.0 - V4.3

Unsupported Hardware:

NetModule Router

NB1310

NB22XX

NB23XX

NB25XX

NB26XX



2 New Features

Case-#	Description
37005	Support for Huawei MU609 The Huawei MU609 modem is now supported.
36290	USSD Codes via CLI The CLI is now able to send/query USSD codes. For instance, one may query the first modem by running: cli send ussd 0 "*100#"
36423	SNMP Admin Access For SNMPv1/v2, it is now possible to specify a whole subnet rather than just a host which will be priviledged for administrative access.
37120	SDK Events We have added an nb_event_msg function which is able to retrieve additional options for an event.
37158	DHCP Hostname The GUI status pages are now listing the hostname of DHCP clients (if provided).



3 Fixes

The following issues and problems have been fixed.

Case-#	Description		
33252	WLAN Chip Reset		
	We have fixed a patch for the Atheros WLAN driver which addresses an issue when stopping the transmit hardware queues upon a reset. The WLAN connection should come back much faster now, it also makes the reset process much more reliable. Thus, this fix will also increase WLAN throughput in general.		
36774	OpenVPN Denial-Of-Service (TLS) According to this announcement, a TLS-enabled OpenVPN server faces a denial of service vulnerability in versions up to 2.3.5. This has been fixed.		
34251	Faulty OpenVPN Config Conversion When upgrading from NRSW 3.6 to 3.7, it may have happened that OpenVPN's internal datagram fragmentation got enabled for clients, which in turn broke tunnel connections with servers that did not support this. The issue has been resolved.		
36303	SDK Configuration Fails The nb_config_set function may have failed in case of too long config requests. This has been fixed.		
35373 36342 37108	SDK Filesystem Issues Under some special circumstances, an SDK script was not able to access all paths of the filesystem. We also fixed a memory corruption bug which lead to the exhaustion of the /tmp filesystem.		
36314	SDK PUT Transfers The nb_transfer_put function failed for uploads larger than 2048 bytes. This has been fixed.		
36805	Link Supervision Fails It may have happened that link supervision bailed out in case the interface was flooded with packets. The system will now wait for up to 10 packets until a valid ICMP reply will be received.		
36886	Connection Issues with MC7710 In very rare cases, establishment of a WWAN link with MC7710 was aborted too early which lead to superfluous redial attempts. This issue has been tracked down.		
36507	Overlapping Networks in IPsec Tunnel It appeared that access to the box was blocked if the remote subnet of an IPsec tunnel included the local subnet, which is possible now.		
36507	WLAN Regulatory Database Updated We have updated the regulatory database which defines the channels and transmit power for WLAN access points. The changes include:		
	•added rules for YT, VI, UG, SR, RE, PY, PF, NI, MW, MU, MQ, MP, MN, KY, GP, GF, ET, CX, BS, AS		
	•added 5490-5710 MHz for BG •added 5825 MHz for KR		



4 Known Issues

Items listed here represent minor problems known at release time. These issues are going to be resolved in a later version.

Case-#	Description	
37225	USSD on Huawei EM770/EM820	
	It is currently not possible to issue USSD queries on Huawei EM770/EM820.	



5 Pitfalls

Items listed as pitfalls are potential problems that may arise because of specific environmental conditions. There are currently no fixes planned for these issues.

Case-#

Description



6 OSS Notice

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)¹, GNU Lesser General Public License (LGPL)² or other open source licenses³.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at router@support.netmodule.com.

¹GPLv2 license is available at http://www.gnu.org/licenses/gpl-2.0.txt

²LGPL license is available at http://www.gnu.org/licenses/lgpl.txt

³OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at http://opensource.org/licenses



7 Change History

Changes:

Version	Date	Name	Reason
1.0	2015-01-28	hess	Release
1.1	2014-10-29	hess	Added OSS Notice

Copyright © 1998 - 2015 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representa-tion or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG. While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG.

All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Meriedweg 11 CH-3172 Niederwangen Switzerland

info@netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at www.netmodule.com.