

# Release Note NRSW 3.8.0.104

**Project Name:** NRSW 3.8

## **Abstract:**

This document represents the release note for NetModule Router Software 3.8.0.104. It informs on new functionality, corrections and known issues of the current software version of NetModule's router series.

## **Keywords:**

NetModule, Software Development, NRSW, Release Note

## **Document Control:**

|                  |                |                   |
|------------------|----------------|-------------------|
| <b>Document:</b> | <b>Version</b> | 1.0               |
|                  | <b>File</b>    | NRSW-RN-3.8.0.104 |
|                  | <b>Status</b>  | Valid             |
| <b>Creation:</b> | <b>Role</b>    | <b>Name</b>       |
|                  | Author         | Benjamin Amsler   |
|                  | Review         | Stefan Schlosser  |
| <b>Approval</b>  | <b>Role</b>    | <b>Name</b>       |
|                  | Technical CEO  | Thomas Siegrist   |

## 1 Release Information

---

### NetModule Router Software:

Version: **3.8.0.104**  
Date: **January 29, 2016**

### Supported Hardware:

| <b>NetModule Router</b> | <b>Hardware Version</b> |
|-------------------------|-------------------------|
| NB1600                  | V1.0 - V3.3             |
| NB2700                  | V1.0 - V2.7             |
| NB2710                  | V1.0 - V2.7             |
| NB3700                  | V2.0 - V4.3             |
| NB3710                  | V2.0 - V4.3             |
| NB3720                  | V2.0 - V4.3             |

### Unsupported Hardware:

**NetModule Router**  
NB1310  
NB22XX  
NB23XX  
NB25XX  
NB26XX

## 2 New Features

---

| Case-#       | Description   |
|--------------|---|
| <b>38412</b> | <b>Increased Volume for Voice Calls</b><br>It is now possible to further increase the volume level for voice calls.               |
| <b>40794</b> | <b>Multicast Downstream Interfaces</b><br>We have added support for setting up multiple downstream interfaces for the IGMP proxy. |
| <b>40520</b> | <b>GPS Supervision</b><br>Supervising the GPS service can be configured now more precisely via the Web Manager.                   |

### 3 Fixes

The following issues and problems have been fixed.

| Case-#         | Description  |
|----------------|--|
| 41161          | <b>SSID With Whitespaces</b><br>The Web Manager ran into an issue if the SSID for a WLAN client contained whitespaces. This has been fixed.  |
| 41139          | <b>WWAN Network Scan</b><br>The Web Manager did not display scanned WWAN networks properly. This has been fixed.   |
| 41086<br>40574 | <b>Time Issues</b><br>chronyd will now update the real time clock if the initial time synchronization failed. We have further upgraded ntpdate to version 4.2.8p2 to bypass any compatibility issues with Microsoft time servers.  |
| 40742          | <b>Forwarding with Extended Routes</b><br>Using extended routes to forward packets to a specific interface failed under some circumstances. This has been fixed.   |
| 41047          | <b>No SNMP WWAN Information</b><br>The nbWwanTable did not provide all SNMP information about the modem status.  |
| 39835<br>40197 | <b>Access to Hosts in Same Private APN</b><br>Modems in Direct IP mode usually require a subnet for setting up the CDC Ethernet interface. However, this potentially broke communication with other hosts in a private APN which held one of these subnet addresses. This has been resolved. |
| 41072<br>40912 | <b>Dialing of WAN Links</b><br>In very rare cases a switchover link has not been dialed. This has been fixed. Further, a link will be established despite of any misconfigured nameservers.  |
| 40824          | <b>Higher Priority for Surveyor</b><br>We have assigned a higher scheduling priority for the surveyor daemon which guarantees a valid operation also under high load.  |
| 41108<br>38465 | <b>WLAN Access-Point Configuration</b><br>It happened that the available WLAN channels for a second WLAN module have not been detected properly. This has been fixed. We have also added the possibility to specify the bandwidth and configure CCMP-only for 802.11n networks.              |
| 40925          | <b>Preferred Service Type on Huawei MU609</b><br>The settings for the preferred service type G2-only on a Huawei MU609 were not correct. This has been fixed.  |
| 40931          | <b>IPsec NAT Address</b><br>Any configured NAT address for IPsec networks has not been set properly. This has been fixed.  |
| 41314          | <b>OpenVPN Expert Mode File</b><br>If an OpenVPN client was configured using an expert mode file and the root certificate authority was not created in advance, the generation of the expert mode file for this tunnel failed. This has been fixed.  |
| 41371          | <b>Reboot After Multiple Failed Dial Attempts</b><br>After a bunch of failed dial attempts with a Huawei MU609 the system may have rebooted sporadically. This has been fixed.   |
| 40928          | <b>No Bootup on NB3700</b><br>We have eliminated a bootup failure which might have happened on certain versions of NB3700.   |
| 41128          | <b>Security Audit USB Autorun</b><br>A security audit on the USB Autorun feature concluded that the procedure can be considered secure. Any potential dictionary attacks are now blocked at a very early stage. We nevertheless encourage customers to use strong passwords.                 |

## 4 Known Issues

---

Items listed here represent minor problems known at release time. These issues will be resolved in a later version.

| Case-#       | Description   |
|--------------|---|
| <b>37225</b> | <b>USSD on Huawei EM770</b><br>USSD queries on Huawei EM770 are not supported.  |
| <b>32507</b> | <b>No VRRP on Bridged Interfaces</b><br>VRRP over bridged interfaces is not implemented.  |
| <b>36992</b> | <b>No SMS Delivery Reports</b><br>SMS delivery reports are currently not possible with Option GTM661/GTM671, Huawei EM820 and Sierra MC7710 modems. |

## 5 Pitfalls

---

Items listed as pitfalls are potential problems that may arise because of specific environmental conditions. There are currently no fixes planned for these issues.

| Case-# | Description |
|--------|-------------|
|--------|-------------|

## 6 OSS Notice

---

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)<sup>1</sup>, GNU Lesser General Public License (LGPL)<sup>2</sup> or other open source licenses<sup>3</sup>.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at [router@support.netmodule.com](mailto:router@support.netmodule.com).

---

<sup>1</sup>GPLv2 license is available at <http://www.gnu.org/licenses/gpl-2.0.txt>

<sup>2</sup>LGPL license is available at <http://www.gnu.org/licenses/lgpl.txt>

<sup>3</sup>OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at <http://opensource.org/licenses>

## 7 Change History

---

| Version | Date       | Name   | Reason  |
|---------|------------|--------|---------|
| 1.0     | 2016-01-29 | amsler | Release |
|         |            |        |         |
|         |            |        |         |
|         |            |        |         |
|         |            |        |         |

### Copyright © 1998 - 2016 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to [info@netmodule.com](mailto:info@netmodule.com) at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG.

All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Meriedweg 11  
 CH-3172 Niederwangen  
 Switzerland  
[info@netmodule.com](mailto:info@netmodule.com)  
 Tel +41 31 985 25 10  
 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at [www.netmodule.com](http://www.netmodule.com).