

CH-3172 Niederwangen Switzerland info@netmodule.com http://www.netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

# Release Note NRSW 4.0.0.109

Project Name: NRSW

# **Abstract:**

This document represents the release note for NetModule Router Software 4.0.0.109. It informs on new functionality, corrections and known issues of the current software version of NetModule's router series.

# **Keywords:**

NetModule, Software Development, NRSW, Release Note

### **Document Control:**

υo	cu	m	en	t:	

Version	1.0
File	NRSW-RN-4.0.0.109
Status	Valid

**Creation:** 

Role	Name
Author	Moritz Rosenthal
Review	Benjamin Amsler

**Approval** 

Role	Name
Director Product Development	Michael Enz



### **1 Release Information**

#### **NetModule Router Software:**

4.0.0.109 Version:

Date: February 03, 2018

### **Supported Hardware:**

NetModule Router	Hardware Versio
NB1600	V1.0 - V3.3
NB2700	V1.0 - V2.7
NB2710	V1.0 - V2.7
NB2800	V1.0 - V1.4
NB3700	V2.0 - V4.3
NB3701	V1.0 - V1.3
NB3710	V2.0 - V4.3
NB3711	V1.0 - V1.3
NB3720	V2.0 - V4.3
NB3800	V1.0 - V1.3

### **Unsupported Hardware:**

#### **NetModule Router**

NB1300 Series

NB2200 Series

NB2300 Series

NB2500 Series

NB2600 Series



Subscribe to our mailing and get the latest news about software releases and much more

2/9 Release Note NRSW 4.0.0.109



# 2 New Features

Case-#

Description



# 3 Fixes

The following issues and problems have been fixed.

Case-#	Description
46376	SSH server certificate download failed
	The certificates which were provided for download from the web GUI were not in the right format to reinstall them into another device. This was fixed.
46383	GUI improvements
49062	Some special characters like '@' or'!' were not allowed as APN password in web interface. This was
49186	fixed.  When SIM cards were switched between WWAN modules there was a misleading warning showing up. This has been fixed.
	After configuration of a new WWAN interface it could happen that the new interface was not shown in the list of configured devices until the page was reloaded. This was fixed.
46742	Linux kernel CVEs
	CVE-2017-7533 A race condition can lead to local user privilege escalation
47196	SDK example script for SMS receive/transmit failed sometimes  The SDK example script on SMS receive/transmit had an error in the DIO handling. This was fixed.  It was improved for better readability and cleaner code as well.
47237	Boot loop after operator error on software update
	We have seen devices to run into a boot loop after the administrator performed a configuration update after a partial software update. The bug fix will prevent any configuration updates via file upload until a pending software update was applied on reboot. Never the less it is recommended to reboot the device after performing a software update.
47491	GPS got stuck under certain condition
	Sometimes the GPS module (issue was seen at ME909u) got stuck and would not produce a fix until system restart. This was fixed.
47552	Memory leak in SMS send function
	When sending from a SSH connection temporary file were sometimes not deleted, if the connection was interrupted early by the SSH client. If that happened very often /tmp/ could fill up with effect to the operating system. That was fixed.
47997	Don't forward packages of local networks
	Packets which belonged to networks of local interfaces were routed over IPsec links, if they were neither originated from nor targeted to the router (iptables FORWARD chain). That was fixed.
48005	SPL update failed
	In very rare occasions it could happen that an update of the SPL boot loader failed. We have seen
	that on devices which were up for about one year without reboot. To guarantee a proper update the updater will check the up-time and reject updates if the device was not rebooted for a long time.
48013	Disabled forwarding of DHCP offers
	In setups with more than one WAN link DHCP offers on one of the WAN links were sometimes
	forwarded to the other WAN interface. This behavior was not intended and got fixed by disabling forwarding on WAN links until the link is fully operational and all firewall rules apply.
48165	GPS supervision
48303	We have seen situations where the GPS failed to provide data, but the supervision did not trigger a restart of the GPS or of the router. The root cause for the missing GPS data was fixed as well as the behavior of the GPS supervision in failure state of the GPS daemon.
48185	Support for Serial interface on NB3701  NB3701 with serial RS232 interface is now fully supported.

Release Note NRSW 4.0.0.109



Case-#	Description
48196	Voice daemon fails and triggers reboot  There have been situations where the voice daemon failed to start and triggered a system reboot.  The voice daemon was fixed.
48252	Group alias of nobody to nogroup added  There was a case where a customer relied on the existence of the system group nobody for advanced expert mode OpenVPN configuration. For backwards compatibility with the existing configuration the group nobody was created as alias to nogroup.
48280	SNMP users not created on configuration update SNMP users were not created when applying a configuration file. Therefor SNMP requests with these user credentials failed. This was fixed.
48352	<b>NB2700 port Ethernet 5 not turned off</b> Even when disabled port Ethernet 5 was not switched off and still showed link activity. The port is now shut down correctly.
48601 48864 49173	SDK improvements  Due to a failure in parameter check nm_modbus_reply could fail even though the given parameters were correct. This was fixed.  The SDK process crashed on the command sha256hash on NB2800 and NB3800 family. This was fixed.  In rare conditions nb_status nb_status returned NULL instead of data even though the request was legit. This was fixed.
48648 48649 48650 48651 48652	Linux Kernel security bug fixes  CVE-2017-16525 Possible attack via crafted USB device in USB serial module  CVE-2017-16531 Possible attack via crafted USB device in kernel USB core  CVE-2017-16534 Possible attack via crafted USB device in kernel USB core  CVE-2017-16535 Possible attack via crafted USB device in kernel USB core  CVE-2017-1000410 Possible remote kernel information leak via Bluetooth L2CAP
48664	VLAN packet loss  If there is a MTU set up on a LAN interface VLAN packets which are routed over this interface will get lost if the VLAN's MTU is not set up accordingly.
48674	MTU setup of VLAN interfaces failed MTU setup was applied to the wrong VLAN interface if there were different VLAN defined on different LAN interfaces. This was fixed.
49098 49101 49102	Security bug fixes CVE-2018-1000007 curl HTTP authentication leak in redirects CVE-2017-8816 curl NTLM buffer overflow via integer overflow CVE-2017-8817 curl FTP wildcard out of bounds read
49118	<b>IPsec expert mode configuration missing in configuration download</b> The IPsec expert mode files were not included into the configuration files that can be downloaded from the web interface. This was fixed.

Release Note NRSW 4.0.0.109 5/9



# 4 Known Issues

Items listed here represent minor problems known at release time. These issues will be resolved in a later version.

Case-#	Description
	<b>Serial interface of NB3701 shows some boot log data</b> Even if the serial interface usage is set to "none" or "device server" some early boot ASCII messages will show up at a speed of 115200 baud per second. This cannot be fixed.

Release Note NRSW 4.0.0.109



7/9

# 5 Pitfalls

Items listed as pitfalls are potential problems that may arise because of specific environmental conditions.

Case-#

Description



#### **6 OSS Notice**

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)<sup>1</sup>, GNU Lesser General Public License (LGPL)<sup>2</sup> or other open source licenses<sup>3</sup>.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at router@support.netmodule.com.

Release Note NRSW 4.0.0.109

<sup>&</sup>lt;sup>1</sup>GPLv2 license is available at http://www.gnu.org/licenses/gpl-2.0.txt

<sup>&</sup>lt;sup>2</sup>LGPL license is available at http://www.gnu.org/licenses/lgpl.txt

<sup>&</sup>lt;sup>3</sup>OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at http://opensource.org/licenses



## 7 Change History

Version	Date	Name	Reason
1.0	2018-02-03	rosenthal	Final

## Copyright © 1998 - 2018 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG.

All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Meriedweg 11 CH-3172 Niederwangen Switzerland info@netmodule.com

Tel +41 31 985 25 10 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at www.netmodule.com.

Release Note NRSW 4.0.0.109 9/9