

Switzerland info@netmodule.com http://www.netmodule.com Tel +41 31 985 25 10

Fax +41 31 985 25 11

# Release Note NRSW 4.1.0.110

Project Name: NRSW

## **Abstract:**

This document represents the release note for NetModule Router Software 4.1.0.110. It informs on new functionality, corrections and known issues of this software version of NetModule's router series in comparison to release 4.1.0.109.

# **Keywords:**

NetModule, Software Development, NRSW, Release Note

#### **Document Control:**

Document:	Version	1.0
	File	NRSW-RN-4.1.0.110

Valid **Status** 

**Creation:** Role Name Author walther Review Benjamin Amsler

**Approval** Role Name Michael Enz **Director Product Development** 



## **1 Release Information**

#### **NetModule Router Software:**

Version: 4.1.0.110
Date: May 08, 2020

## **Supported Hardware:**

NetModule Router	<b>Hardware Version</b>
NB800	V2.0 - V2.2
NB1600	V1.0 - V3.3
NB2700	V1.0 - V2.7
NB2710	V1.0 - V2.7
NB2800	V1.0 - V1.4
NB3700	V2.0 - V4.4
NB3701	V1.0 - V1.5
NB3710	V2.0 - V4.3
NB3711	V1.0 - V1.5
NB3720	V2.0 - V4.3
NB3800	V1.0 - V1.5

## **Unsupported Hardware:**

#### **NetModule Router**

NB1300 Series

NB1601 Series

NB1800 Series

NB2200 Series

NB2300 Series

NB2500 Series

NB2600 Series



Subscribe to our mailing and get the latest news about software releases and much more

Release Note NRSW 4.1.0.110 2/8



# 2 New Features

Case-#	Description	
61270	Increase maximum number of static DHCP hosts It's now possible to configure up to 70 static DHCP host entries.	

Release Note NRSW 4.1.0.110 3/8



# 3 Security Fixes

The following security relevant issues have been fixed.

Case-#	Description
61646	Security fixes in 3rd party and open source packages CVE-2020-8597: pppd remote code execution in EAP code

Release Note NRSW 4.1.0.110 4/8



# 4 Fixes

The following issues and problems have been fixed.

Case-#	Description		
59337 60390	GUI improvements  The required RSSI value for mobile interfaces was set to 100 dBm automatically without interaction of the customer. That has been fixed.  IPsec network configuration allows to configure overlapping networks for local and remote side now.		
59801	NB1800 suddenly reboots Reset loops could occur while using the new revision of modem modules. That has been fixed.		
60135	SDK improvements A typo in the example script serial-tcp-broadcast.are was fixed.		
60439	<b>Toby-L2 initial registration</b> While using a Toby-L2 module the initial registration could fail when no 2G connection is currently available. That has been fixed.		
60673	Possible LTE connection loss  Devices with Toby-L2 LTE modules faced sporadically connection loss. In some cases the connection could not be reestablished until reboot. This was fixed.		
62113	Reset of GNSS module could fail There had been situtations where the GNSS supervision failed to reset a GNSS module correctly. In that case no GNSS fix was available until the next system reboot. This was fixed.		
62368	Installing a software release could lead to loss of stored factory configuration After installing another software release the factory configuration manually stored by the customer was lost. That has been fixed.		

Release Note NRSW 4.1.0.110 5/8



#### **5 ECC conversion**

The flash on NB1600, NB2700, NB2710, NB3700, NB3710 and NB3720 provides an automated error correction using ECC. With release 4.1.0.100 we changed the ECC length from 1-bit ECC to 4-bit ECC which provides better error correction. On first boot after the update was performed the data on the flash is automatically converted to use the new ECC setup. While this conversion is performed the LEDs show a running light for about 30 seconds.

If you switch back to an older software release like 4.0.0 the migration is reverted.

We tested updates and down-grades to and from 4.0.0 and 3.8.0. Updates to or from older versions are not supported. If you run an older release or want to downgrade to an older release or a feature release like 3.8.2 you are advised to migrate via 4.0.0 as an intermediate release.

To revert the migration on downgrade the SPL boot loader release 4.1.0 stays in place. It can be downgraded in a second sofware update process initiated from the target release after the first reboot.

Software updates with recovery images require special attention. You must not use recovery images 4.0.0 and older for systems running 4.1.0 and newer. If you want to use recovery images please contact our support at router@support.netmodule.com.



#### **6 OSS Notice**

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)<sup>1</sup>, GNU Lesser General Public License (LGPL)<sup>2</sup> or other open source licenses<sup>3</sup>.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at router@support.netmodule.com.

Release Note NRSW 4.1.0.110 7/8

<sup>&</sup>lt;sup>1</sup>GPLv2 license is available at http://www.gnu.org/licenses/gpl-2.0.txt

<sup>&</sup>lt;sup>2</sup>LGPL license is available at http://www.gnu.org/licenses/lgpl.txt

<sup>&</sup>lt;sup>3</sup>OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at http://opensource.org/licenses



## 7 Change History

Version	Date	Name	Reason
0.1	April 30, 2020	Moritz Rosenthal	preliminary version

# Copyright © 1998 - 2020 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG.

All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at www.netmodule.com.

Release Note NRSW 4.1.0.110