

# Release Note NRSW 4.3.0.100

---

**Project Name:** NRSW

## Abstract:

This document represents the release note for NetModule Router Software 4.3.0.100. It informs on new functionality, corrections and known issues of this software version of NetModule's router series in comparison to release 4.2.0.103.

## Keywords:

NetModule, Software Development, NRSW, Release Note

## Document Control:

<b>Document:</b>	<b>Version</b>	1.1
	<b>File</b>	NRSW-RN-4.3.0.100
	<b>Status</b>	Valid
<b>Creation:</b>	<b>Role</b>	<b>Name</b>
	Author	Moritz Rosenthal
	Review	Benjamin Amsler
<b>Approval</b>	<b>Role</b>	<b>Name</b>
	Director Product Development	Michael Enz

## 1 Release Information

---

### NetModule Router Software:

Version: **4.3.0.100**  
Date: **July 02, 2019**

### Supported Hardware:

<b>NetModule Router</b>	<b>Hardware Version</b>
NB800	V2.0 - V2.2
NB1600	V1.0 - V3.3
NB1601	V1.0 - V1.3
NB1800	V2.4 - V2.6
NB1810	V2.4 - V2.6
NB2700	V1.0 - V2.7
NB2710	V1.0 - V2.7
NB2800	V1.0 - V1.4
NB3700	V2.0 - V4.3
NB3701	V1.0 - V1.4
NB3710	V2.0 - V4.3
NB3711	V1.0 - V1.4
NB3720	V2.0 - V4.3
NB3800	V1.0 - V1.4

### Unsupported Hardware:

**NetModule Router**  
NB1300 Series  
NB2200 Series  
NB2300 Series  
NB2500 Series  
NB2600 Series



**NetModule Insights**

Subscribe to our mailing and get the latest news about software releases and much more

## 2 New Features

Case-#	Description
38404	<b>WLAN fast roaming</b> Fast Transition (802.11r) and pre-authentication is now supported.
45743	<b>WLAN band steering</b> It is now possible to steer WLAN clients from one frequency band to another.
48541	<b>L2TPv3 support</b> L2TPv3 tunnels can be configured and bridged to local interfaces.
48570 54206 55902 56101 56112	<b>Update of 3rd party software packages</b> Linux Kernel was updated to LTS release 4.19 curl was updated to version 7.64.0 OpenSSL was updated to 1.0.2r OpenVPN was updated to 2.4.6 Busybox was updated to 1.28.4
49120	<b>Allow multiple VRRP instances</b> You can now setup up to 4 instances of VRRP for different networks.
53015	<b>Disable low data rates as WLAN access point</b> It is now possible to disable low data rates in WLAN 2.4 GHz frequency band to avoid sticky clients and decrease airtime utilization.
53663	<b>Improved voice call quality</b> On NB1601 the voice quality was improved by better software sound processing.
54033 54934	<b>Support for new hardware</b> The CanGI shield providing a GNSS receiver and a CAN interface is now supported for NB800.
56765	<b>Wireless regulatory</b> The wireless regulatory database has been updated to version 2019-04-23.
57046	<b>DIO Support</b> Support of new DIO Extension Module for NB2800 and NB3800

---

### 3 New Beta Features

---

These features might undergo minor changes in the next releases.

Case-#	Description
<b>54302</b>	<b>Support for Netflow</b> WLAN interfaces can now be monitored using the Netflow protocol.

## 4 Fixes

The following issues and problems have been fixed.

Case-#	Description
<b>49893</b>	<b>Windows NTP Server</b> The NTP client had some problems while receiving NTP data from a Windows NTP server. This has been fixed
<b>53789</b>	<b>Improved VPN performance for NB1601</b> Improved transfer performance with IPsec and OpenVPN for NB1601. Scheduling in the software was improved to resolve the issue.
<b>54456</b>	<b>Failure in configuration conversion</b> Applying a configuration from NRSW release 3.8.0 and before could result in invalid IPsec connection for certain settings. This was fixed.
<b>55453</b>	<b>LED indicators</b> On connection establishment the WLAN LED on WLAN client could show red blinking signal, which is not described in the manual. This was fixed: The LED will always blink green until process of connection establishment was finished and then switches color to indicate the signal quality.
<b>56534</b>	<b>SNMP renaming of interface</b> IF-MIB entries were not updated after an interface was renamed. This has been fixed
<b>56579</b>	<b>Toby-L2 transparent routing</b> Transparent routing was not possible with an ublox Toby-L2 modem. This has been fixed in the router SW, but also requires a modem firmware update. For detailed information about supported firmware for the different Toby-L2 modems please contact our support.
<b>56718</b>	<b>Initial Setup</b> After the first initial login the external USB port was not disabled by default. This has been fixed. If you did the initial setup of your device with software release 4.1.0.105 to 4.2.0.104 you should review if the setup of the USB port is correct. Disabling the port explicitly via command line interface or web interface is not affected.
<b>56829</b>	<b>SIM handling improved</b> Due to timing issues it could happen that two modules were reported as connected to the same SIM card. In this case the connection was not established after configuration until a reboot was performed. This has been fixed. It could only happen if the device is configured via web interface. Configuration updates via configuration file or on SW update were not affected.
<b>56863</b>	<b>Ethernet link detection failed on NB1601</b> With some Ethernet switches there were situations where the link detection on NB1601 failed. This was fixed by tuning the settings of the internal Ethernet chip-set of the NB1601.
<b>57073</b>	<b>NTP server reported wrong stratum</b> If the device does not have any reliable time source like an external NTP server or GNSS after boot the NTP server reported a local stratum of 15 which is rejected by most NTP clients as invalid, but never the less not correct. An NTP server which is not synchronized should report 0 instead. This was fixed.
<b>57154</b> <b>57155</b>	<b>SNMP could not be used with DES and AES</b> Setting up SNMP with DES and AES failed due to a missing dependency for OpenSSL in SNMP server. This was fixed.
<b>57360</b>	<b>WLAN channels not selectable</b> If United Arab Emirates was selected as location, 5GHz WLAN channels 36, 40, 44 and 48 were not offered for selection even though they are allowed to be used.

---

Case-#	Description
<b>57540</b>	<b>WLAN client flaky under heavy load</b> A WLAN client configured on NB800 and NB1601 was sporadically wrongly set down in situations with heavy traffic load. This was caused by invalid quality levels reported by the WLAN chipset. This was fixed by changing the chip settings and the procedure of supervision. The fix also increased the throughput in client mode.

---

## 5 ECC conversion

---

The flash on NB1600, NB2700, NB2710, NB3700, NB3710 and NB3720 provides an automated error correction using ECC. With release 4.1.0.100 we changed the ECC length from 1-bit ECC to 4-bit ECC which provides better error correction. On first boot after the update was performed the data on the flash is automatically converted to use the new ECC setup. While this conversion is performed the LEDs show a running light for about 30 seconds.

If you switch back to an older software release like 4.0.0 the migration is reverted.

We tested updates and down-grades to and from 4.0.0 and 3.8.0. Updates to or from older versions are not supported. If you run an older release or want to downgrade to an older release or a feature release like 3.8.2 you are advised to migrate via 4.0.0 as an intermediate release.

To revert the migration on downgrade the SPL boot loader release 4.1.0 stays in place. It can be downgraded in a second software update process initiated from the target release after the first reboot.

Software updates with recovery images require special attention. You must not use recovery images 4.0.0 and older for systems running 4.1.0 and newer. If you want to use recovery images please contact our support at [router@support.netmodule.com](mailto:router@support.netmodule.com).



## 6 OSS Notice

---

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)<sup>1</sup>, GNU Lesser General Public License (LGPL)<sup>2</sup> or other open source licenses<sup>3</sup>.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at [router@support.netmodule.com](mailto:router@support.netmodule.com).

---

<sup>1</sup>GPLv2 license is available at <http://www.gnu.org/licenses/gpl-2.0.txt>

<sup>2</sup>LGPL license is available at <http://www.gnu.org/licenses/lgpl.txt>

<sup>3</sup>OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at <http://opensource.org/licenses>

## 7 Change History

---

Version	Date	Name	Reason
1.1	July 2nd, 2019	Moritz Rosenthal	Added missing information on Cases 53789 and 49120
1.0	June 24th, 2019	Moritz Rosenthal	Final

### Copyright © 1998 - 2019 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to [info@netmodule.com](mailto:info@netmodule.com) at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG.

All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Maulbeerstrasse 10  
 CH-3011 Bern  
 Switzerland  
[info@netmodule.com](mailto:info@netmodule.com)  
 Tel +41 31 985 25 10  
 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at [www.netmodule.com](http://www.netmodule.com).