

info@netmodule.com http://www.netmodule.com Tel +41 31 985 25 10

Fax +41 31 985 25 11

Release Note NRSW 4.4.0.103

Project Name: NRSW

Abstract:

This document represents the release note for NetModule Router Software 4.4.0.103. It informs on new functionality, corrections and known issues of this software version of NetModule's router series in comparison to release 4.4.0.102.

Keywords:

NetModule, Software Development, NRSW, Release Note

Document Control:

Document:	version	1.0
	File	NRSW-RN-4.4.0.103

Valid **Status**

Creation: Role Author Moritz Rosenthal Review Benjamin Amsler

Approval Role Name Michael Enz **Director Product Development**



1 Release Information

NetModule Router Software:

Version: **4.4.0.103**

Date: February 24, 2020

Supported Hardware:

NetModule Router	Hardware Version
NB800	V2.0 - V2.2, V3.2 (Rev. B02)
NB1600	V1.0 - V3.3
NB1601	V1.0 - V1.3
NB1800	V2.4 - V2.6
NB1810	V2.4 - V2.6
NB2700	V1.0 - V2.7
NB2710	V1.0 - V2.7
NB2800	V1.0 - V1.4
NB3700	V2.0 - V4.4
NB3701	V1.0 - V1.4
NB3710	V2.0 - V4.3
NB3711	V1.0 - V1.4
NB3720	V2.0 - V4.3
NB3800	V1.0 - V1.4

Unsupported Hardware:

NetModule Router

NB1300 Series

NB2200 Series

NB2300 Series

NB2500 Series

NB2600 Series

Release Note NRSW 4.4.0.103 2/8





NetModule Insights
Subscribe to our mailing and get the latest
news about software releases and much more

Release Note NRSW 4.4.0.103 3/8



2 New Features

Case-#	Description		
52473	QoS with bridged WLAN interfaces QoS settings were not possible for WLAN access point mode if the WLAN interface was bridged. That has been changed.		
57642	IPsec improvements IPsec tunnels can be enabled and disabled individually now.		
59235	Support for new router model NB2810 Added software support for the new NB2810 router.		
59534	GUI improvements Mark WLAN 5 GHz indoor channels as indoor.		
59828	Prevent down-grade to incompatible version If you want to downgrade to an older release, you may have to install intermediate releases. Normally that's the latest release of the major version of the desired software. The Update process will detect the release number of the uploaded image and prevent installation of invalid releases.		
60086	IPsec The number of configurable IPsec tunnels was increased to 10.		
60335 60336	New Netmodule CI		
60475	Added support for passive CAN interfaces on NB800 and NB1601 There is a new hardware extension providing passive CAN interfaces for NB800 and NB1601. These interfaces are supported now. Passive interfaces are designed so that they can only be used for listening on the CAN bus, while the software is unable to send anything on the bus. Also enabling termination resistors for the bus by software is not possible on the passive interfaces.		
60650	Active GNSS antenna for NB1800 and NB1810 New HW releases of NB1800 and NB1810 support active GNSS antenna. It can be configured via GNSS settings now.		

Release Note NRSW 4.4.0.103 4/8



3 Fixes

The following issues and problems have been fixed.

Case-#	Description		
53872	ublox Toby-L2 SMS handling While receiving big SMS messages the evaluation of the SMS message index could lead to wrong results. This has been fixed.		
59320	IPsec tunnel configuration failed It could happen that IPsec was not correctly activated after installing a user-configuration file. This happened reproducible with special configuration settings. If IPsec came up after applying a configuration (most common scenarios), then you were not affected.		
59337 60105 60390	GUI improvements The required RSSI value for mobile interfaces was set to 100 dBm automatically without interaction of the customer. That has been fixed. NTP-Server did not allow to set up access from world (0.0.0.0/0). That was fixed. IPsec network configuration allows to configure overlapping networks for local and remote side now.		
59345	File transfer to and from NB3701 and 3711 very slow Ethernet traffic on NB3701 and NB3711 were very slow for traffic which was not routed, but had the router itself as target (i.e. software update on web interface via LAN). The failure in the Interface setup in Linux kernel was fixed and all interfaces operate at normal speed again.		
59469	ublox SAM-M8Q module info The ublox SAM-M8Q was displayed as ublox NEO-M8L with Beidou support. That has been fixed.		
59797	ublox Toby-L2 I2S communication The I2S communication could fail while using a ublox Toby-L2 module. That has been fixed.		
59801	NB1800 suddenly reboots Reset loops could occur while using the new revision of modem modules. That has been fixed.		
60135	SDK improvements A typo in the example script serial-tcp-broadcast.are was fixed.		
60439	Toby-L2 initial registration While using a Toby-L2 module the initial registration could fail when no 2G connection is currently available. That has been fixed.		
60535	Control of CAN termination resistors fixed On NB800 Rev. B02 and NB1601 control of the CAN termination registers was swapped. Meaning that when the termination resistors for CAN0 were enabled in the software the resisters were actually enabled for CAN1 in the hardware. This has been fixed.		

Release Note NRSW 4.4.0.103 5/8



4 ECC conversion

The flash on NB1600, NB2700, NB2710, NB3700, NB3710 and NB3720 provides an automated error correction using ECC. With release 4.1.0.100 we changed the ECC length from 1-bit ECC to 4-bit ECC which provides better error correction. On first boot after the update was performed the data on the flash is automatically converted to use the new ECC setup. While this conversion is performed the LEDs show a running light for about 30 seconds.

If you switch back to an older software release like 4.0.0 the migration is reverted.

We tested updates and down-grades to and from 4.0.0 and 3.8.0. Updates to or from older versions are not supported. If you run an older release or want to downgrade to an older release or a feature release like 3.8.2 you are advised to migrate via 4.0.0 as an intermediate release.

To revert the migration on downgrade the SPL boot loader release 4.1.0 stays in place. It can be downgraded in a second sofware update process initiated from the target release after the first reboot.

Software updates with recovery images require special attention. You must not use recovery images 4.0.0 and older for systems running 4.1.0 and newer. If you want to use recovery images please contact our support at router@support.netmodule.com.

Release Note NRSW 4.4.0.103



5 OSS Notice

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)¹, GNU Lesser General Public License (LGPL)² or other open source licenses³.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at router@support.netmodule.com.

Release Note NRSW 4.4.0.103 7/8

¹GPLv2 license is available at http://www.gnu.org/licenses/gpl-2.0.txt

²LGPL license is available at http://www.gnu.org/licenses/lgpl.txt

³OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at http://opensource.org/licenses



6 Change History

Version	Date	Name	Reason
1.0	January 23, 2020	Moritz Rosenthal	Final

Copyright © 1998 - 2020 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG.

All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at www.netmodule.com.

Release Note NRSW 4.4.0.103