

Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com http://www.netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

Release Note NRSW 4.4.0.108

Project Name: NRSW

Abstract:

This document represents the release note for NetModule Router Software 4.4.0.108. It informs on new functionality, corrections and known issues of this software version of NetModule's router series.

Keywords:

NetModule, Software Development, NRSW, Release Note

Document Control:

Document:	Version	1.1
	File	NRSW-RN-4.4.0.108
	Status	Final

RoleNameAuthorMoritz RosenthalReviewBanjamin Amsler

Approval Role Name

Director Product Development Benjamin Amsler



1 Release Information

NetModule Router Software:

Version: 4.4.0.108
Date: Apr 28, 2021

Supported Hardware:

NetModule Router	Hardware Version
NB800	V2.0 - V2.2, V3.2 (Rev. B02)
NB1600	V1.0 - V3.3
NB1601	V1.0 - V1.5
NB1800	V2.4 - V2.6
NB1810	V2.4 - V2.6
NB2700	V1.0 - V2.7
NB2710	V1.0 - V2.7
NB2800	V1.0 - V1.4
NB2810	V1.2
NB3700	V2.0 - V4.4
NB3701	V1.0 - V1.5
NB3710	V2.0 - V4.3
NB3711	V1.0 - V1.5
NB3720	V2.0 - V4.3

V1.0 - V1.5

Unsupported Hardware:

NetModule Router

NB1300 Series

NB3800

NB2200 Series

NB2300 Series

NB2500 Series

NB2600 Series



NetModule Insights
Subscribe to our mailing and get the latest news about software releases and much more





2 New Features

Case-#	Description
63455 65359 65719	GUI improvements IPsec source IP can now be configured. It is possible now to run tcpdump on all interfaces at the same time. This is helpful in situations where you try to debug a misconfiguration in your routing setup where you don't know on which interface traffic will be routed. Maximum rate of SMS send events now configurable.



3 Security Fixes

The following security relevant issues have been fixed.

Case-#	Description	
70209 70210 70211 70217	Prevent stored Cross-Site-Scripting attacks Some user settings were displayed directly in the web interface making it vulnerable to Stored Cross-Site-Scripting attacks. To exploit this vulnerability administrative access was required.	
70212	Authenticated read and delete of arbitrary files via web interface A directory traversal mistake made it possible for logged-in administrative users to read and delete arbitrary files on the file system.	
70213	GUI vulnerable to Cross-Site-Reques-Forgery A CSRF-Token was introduced to prevent targeted attacks to logged-in administrators.	
70214	Users with CLI shell access could extend their privileges For users with CLI shell access it was possible to open a regular linux command line shell.	
70215	Information breach for user logged in to shell A user with limited rights who was logged in to a shell (for example via SSH, Telnet or serial interface) was able to request confidential configuration values. Non-Administrative users are not able to log in into a shell and therefore this attack should not be exploitable, never the less the access rights to the configuration management were fixed.	
70216	Incorrect permission assignment for critical recources Some files like /etc/shadow were readable by non-adminitator users. This is a potential security risk. It is not possible to configure a login with shell access or read the file system for non-administrative users, but never the less the access was restricted to root users as it is generally recommended.	



4 Fixes

The following issues and problems have been fixed.

Case-#	Description	
59872 62595 65397 66328 67830 68007 69152 69624 70164 70165	If an OpenVPN client was deleted via web interface it could happen that the certificate association of other remaining OpenVPN configurations could be mixed up. Deleting firewall groups mixed up the order of groups. It was not possible to select UTC timezone with daylight saving was not possible. This was fixed. Switching the interface of one of the VLAN from one LAN to another could fail in some situations. This was fixed. On edit of firewall rules the wrong group was preselected. This was fixed. After removing an IPsec tunnel, wrong default values were proposed in the web interface. In some situations the IPsec status shown in the web interface was wrong after connection loss. IPsec PSK did handle ampersand character incorrectly. This was fixed. On change of remote IP settings of an existing IPSec configuration some firewall rules were not changed correctly. This was fixed. IPsec Common Name did not handle blank spaces correctly. Blanks are allowed now.	
62594	IPsec dependent firewall rules not deleted if IPsec was disabled	
63374	GUI improvement PPTP was missing username and password fields in some situations.	
65199	SDK improvements nb_status("gnss").GNSS1_VERTICAL_SPEED could crash the SDK host.	
65400	GSM calls not processed Sometimes incoming GSM calls were missed by the system. This was fixed.	
65858	Large techsupport files truncated It could happen to be incomplete due to missing disk space. This was fixed by not buffering the content.	
66239	Manual provider selection was ignored with Toby-L2 LTE modules Due to a configuration failure devices with Toby-L2 could connect to wrong network if manual provider selection was enabled. This was fixed.	
67967	SYS LED wrongly indicates error state In rare situations the SYS LED of NB1800 indicated an error even though the system was not in error state. This was fixed.	
69956	IP packet loss on LTE modules IP packets with a specific length were lost on Transmission via LTE link on Toby-L2 in some rare situations. The USB communication was changed to fix this systematic failure.	



5 Pitfalls

Items listed as pitfalls are potential problems that may arise because of specific environmental conditions.

Case-#	Description
71447	Potential loss of LTE connection Devices with Toby-L2 LTE modules may occasionally loose LTE connection. This is persistent until the Router or the LTE connection is restarted for example by the Link Supervision. It is recommended to properly configure Link Supervision if the device is supposed to work autonomously or if the WAN link is the only maintenance connection in the field application.



6 ECC conversion

The flash on NB1600, NB2700, NB2710, NB3700, NB3710 and NB3720 provides an automated error correction using ECC. With release 4.1.0.100 we changed the ECC length from 1-bit ECC to 4-bit ECC which provides better error correction. On first boot after the update was performed the data on the flash is automatically converted to use the new ECC setup. While this conversion is performed the LEDs show a running light for about 30 seconds.

If you switch back to an older software release like 4.0.0 the migration is reverted.

We tested updates and down-grades to and from 4.0.0 and 3.8.0. Updates to or from older versions are not supported. If you run an older release or want to downgrade to an older release or a feature release like 3.8.2 you are advised to migrate via 4.0.0 as an intermediate release.

To revert the migration on downgrade the SPL boot loader release 4.1.0 stays in place. It can be downgraded in a second sofware update process initiated from the target release after the first reboot.

Software updates with recovery images require special attention. You must not use recovery images 4.0.0 and older for systems running 4.1.0 and newer. If you want to use recovery images please contact our support at router@support.netmodule.com



7 OSS Notice

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)¹, GNU Lesser General Public License (LGPL)² or other open source licenses³.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at router@support.netmodule.com.

¹GPLv2 license is available at http://www.gnu.org/licenses/gpl-2.0.txt

²LGPL license is available at http://www.gnu.org/licenses/lgpl.txt

³OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at http://opensource.org/licenses



8 Change History

Version	Date	Name	Reason
1.1	Apr 28, 2021	Moritz Rosenthal	Additional information on case 71447
1.0	Mar 19, 2021	Moritz Rosenthal	Release note
0.1	Mar 15, 2021	Moritz Rosenthal	First draft

Copyright © 1998 - 2021 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG. All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at www.netmodule.com.