

Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com http://www.netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

# Release Note NRSW 4.4.0.109

Project Name: NRSW

### **Abstract:**

This document represents the release note for NetModule Router Software 4.4.0.109. It informs on new functionality, corrections and known issues of this software version of NetModule's router series.

# **Keywords:**

NetModule, Software Development, NRSW, Release Note

#### **Document Control:**

Document:	Version	1.0
	File	NRSW-RN-4.4.0.109
	Status	Final

 Role
 Name

 Author
 Moritz Rosenthal

 Review
 Benjamin Amsler

Approval Role Name

Director Product Development Benjamin Amsler



#### 1 Release Information

#### **NetModule Router Software:**

4.4.0.109 Version: Date: May 7, 2021

#### **Supported Hardware:**

NetModule Router	Hardware Version
NB800	V2.0 - V2.2, V3.2 (Rev. B02)
NB1600	V1.0 - V3.3
NB1601	V1.0 - V1.5
NB1800	V2.4 - V2.6
NB1810	V2.4 - V2.6
NB2700	V1.0 - V2.7
NB2710	V1.0 - V2.7
NB2800	V1.0 - V1.4
NB2810	V1.2
NB3700	V2.0 - V4.4
NB3701	V1.0 - V1.5
NB3710	V2.0 - V4.3
NB3711	V1.0 - V1.5
NB3720	V2.0 - V4.3
NB3800	V1.0 - V1.5

#### **Unsupported Hardware:**

#### **NetModule Router**

NB1300 Series

NB2200 Series

NB2300 Series

NB2500 Series

NB2600 Series



NetModule Insights
Subscribe to our mailing and get the latest news about software releases and much more





## 2 Fixes

The following issues and problems have been fixed.

Case-#	Description		
70274	SIM communication failures  Some rare SIM card types were not recognized by the Toby-L2 LTE modems. If your SIM card is not recognized, please update the modem firmware to version higher than 16 and use the latest NRSW software release.		
70839	Misleading logging in situations with poor LTE coverage If the Toby-L2 LTE module lost connection to the network the system logging showed errors in the AT command communication. The modem communication was fixed preventing failing commands.		
71032	SDK improvements  The example script serial-tcp-broadcast.are contained a semantic failure. This was fixed.		
71322	Possible timeout in AT command communication A failure in the timeout calculation could lead to AT command interface errors. This was fixed.		
71447	Potential loss of LTE connection  Devices with Toby-L2 LTE modules did occasionally loose LTE connection. This was persistent until the Router or the LTE connection is restarted for example by the Link Supervision. It is recommended to properly configure Link Supervision if the device is supposed to work autonomously or if the WAN link is the only maintenance connection in the field application.		



#### 3 ECC conversion

The flash on NB1600, NB2700, NB2710, NB3700, NB3710 and NB3720 provides an automated error correction using ECC. With release 4.1.0.100 we changed the ECC length from 1-bit ECC to 4-bit ECC which provides better error correction. On first boot after the update was performed the data on the flash is automatically converted to use the new ECC setup. While this conversion is performed the LEDs show a running light for about 30 seconds.

If you switch back to an older software release like 4.0.0 the migration is reverted.

We tested updates and down-grades to and from 4.0.0 and 3.8.0. Updates to or from older versions are not supported. If you run an older release or want to downgrade to an older release or a feature release like 3.8.2 you are advised to migrate via 4.0.0 as an intermediate release.

To revert the migration on downgrade the SPL boot loader release 4.1.0 stays in place. It can be downgraded in a second sofware update process initiated from the target release after the first reboot.

Software updates with recovery images require special attention. You must not use recovery images 4.0.0 and older for systems running 4.1.0 and newer.

If you want to use recovery images please contact our support at router@support.netmodule.com.



#### **4 OSS Notice**

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)<sup>1</sup>, GNU Lesser General Public License (LGPL)<sup>2</sup> or other open source licenses<sup>3</sup>.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at router@support.netmodule.com.

<sup>&</sup>lt;sup>1</sup>GPLv2 license is available at http://www.gnu.org/licenses/gpl-2.0.txt

<sup>&</sup>lt;sup>2</sup>LGPL license is available at http://www.gnu.org/licenses/lgpl.txt

<sup>&</sup>lt;sup>3</sup>OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at http://opensource.org/licenses



#### 5 Change History

Version	Date	Name	Reason
1.0	May 7, 2021	Moritz Rosenthal	Final release notes

#### Copyright © 1998 - 2021 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG. All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com

Tel +41 31 985 25 10 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at www.netmodule.com.