

Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com http://www.netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

Release Note NRSW 4.8.0.101

Project Name: NRSW

Abstract:

This document represents the release note for NetModule Router Software 4.8.0.101. It informs on new functionality, corrections and known issues of this software version of NetModule's router series.

Keywords:

NetModule, Software Development, NRSW, Release Note

Document Control:

Document:	Version	1.0
	File	NRSW-RN-4.8.0.101
	Status	Final

 Role
 Name

 Author
 Felix Kopf

 Review
 Friedrich Hausmann

Approval Role Name

Director Product Development Benjamin Amsler



1 Release Information

NetModule Router Software:

Version: 4.8.0.101
Date: Jul 31, 2023

Supported Hardware:

NetModule Router Hardware Version

NB800 V2.0 - V2.2, V3.2 (Rev. B02 - B03)

NG800 V3.0 - V3.2 NB1601 V1.0 - V1.7 NB1800 V2.4 - V2.6 NB1810 V2.4 - V2.6 NB2800 V1.0 - V1.4 NB2810 V1.2

NB3701 V1.0 - V1.10 NB3800 V1.0 - V1.10

Unsupported Hardware:

NetModule Router

NB1300 Series

NB1600 Series

NB2200 Series

NB2300 Series

NB2500 Series

NB2600 Series

NB2700 Series

NB3700 Series

NB3711

NetModule Insights

Subscribe to our mailing and get the latest news about software releases and much more





2 Security Fixes

The following security relevant issues have been fixed.

Case-#	Description	
83033	Security fixes A vulnerability in the web interface that allowed authenticated users to execute code remotely was fixed.	



3 Fixes

The following issues and problems have been fixed.

Case-#	Description	
49356	SDK fixes The Arena SDK function json_encode now behaves according to the JSON standard.	
82444	WLAN Roaming When roaming as a client between multiple access points, sometimes the link was taken down during the change from one access point to another. This issue has been fixed.	
83032	Firewall/IPsec Access to local services on the router itself is no longer disabled for setups with an active IPsec connection configured to use IPsec networks with NAT.	
83034	GNSS fix On some hardware configurations GNSS would be unavailable after a software update to 4.8.0.100. This is fixed.	



4 OSS Notice

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)¹, GNU Lesser General Public License (LGPL)² or other open source licenses³.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at router@support.netmodule.com.

¹GPLv2 license is available at http://www.gnu.org/licenses/gpl-2.0.txt

²LGPL license is available at http://www.gnu.org/licenses/lgpl.txt

³OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at http://opensource.org/licenses



5 Change History

Version	Date	Name	Reason
1.0	Jul 31, 2023	Felix Kopf	Final version

Copyright © 1998 - 2023 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG. All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com

Tel +41 31 985 25 10 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at www.netmodule.com.